

DIRECTIONS FOR USE

Gekko G54 adhesive canister system is designed for bonding carpets to subfloors. Gekko G54 exhibits a fast drying contact adhesive system with a long open time & good heat resistance. Immediate permanent bonds can be achieved by double-sided applications onto most substrates. Subfloors should be prepared in accordance with recommendations stated on the technical data sheet.

SHAKE WELL BEFORE USE. Hold spray gun tip approx. 10 - 15cm from the surface to be covered and apply even coats to both surfaces. Do not allow it to concentrate or puddle in one area. Once adhesive has tacked off, generally within 1 - 3 minutes, contact bond can be made. To apply adequate pressure a pressure roller must be used. Application temperature should be between 5 and 30°C

HANDLING AND STORAGE

Do not store at temperatures over 50°C. Do not thin or reactivate with solvents. Do not incinerate. Keep away from sources of ignition. Test for suitability before use. Avoid exposure to direct sunlight. Do not store directly on concrete floor. For optimum performance, store at 18°C during use, but must always be done above 10°C. When connected, keep valve open and hose pressurised at all times. Always test Gekko G54 to determine suitability for your particular application prior to use in production.

HAZARDS AND PRECAUTIONS

DANGER

H229	Pressurised container: may burst if heated
H222	Extremely flammable aerosol
H312+H332	Harmful in contact with skin or if inhaled
H315	Causes skin irritation
H319	Causes serious eye irritation
H336	May cause drowsiness or dizziness
H411	Toxic to aquatic life with long lasting effects
P210	Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking
P304+P340	IF INHALED: Remove person to fresh air and keep comfortable for breathing
P305+P351+P338	IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do so. Continue rinsing.
P308+P313	IF exposed or concerned: Get medical advice/attention.
P410+P412	Protect from sunlight. Do not expose to temperatures exceeding 50°C/122°F
P501	Dispose of contents/container in accordance with national regulations

UN1950 Aerosol



DISTRIBUTED BY:

Look Floors

A division of Flooring Wholesale Limited

Branches Nationwide


www.lookfloors.co.nz

PO Box 112 027, Penrose Auckland 1642

GENERAL PURPOSE CONTACT

G54

500ml



GEKKO™
Stick With Us!



Gekko Industries Ltd
7 Flowers Hill
Brislington
Bristol
BS4 5JJ

0844 915 0159

gekko-adhesives.com